Objective: Minimize Impact of Aging Plant.

Measures: Availability

Initiatives: Install new burners and elbows during Unit 2 Outage.

Advanced Burner Technologies, A Siemens Company, was contracted to provide redesigned burner injectors and flat back elbows under an agreement with Siemens. The injector is the internals of the burner which includes the coal barrel, the burner tip and the inner air assembly. The new design included lining the barrel with alumina pipe brick and replacing the transition piece between the barrel and the tip from carbon steel to 253 MA stainless steel. The flowered tip was changed to minimize the impact angle and the interior ridges were sprayed with tungsten carbide for higher erosion resistance. A flat back elbow with ABT's fuel distributor replaced the sweep elbow.

All 48 new injectors and elbows arrived in time to be replaced during the Spring 2008 Planned Outage. AP&F was contracted to remove the old elbows and injectors and install the new injectors and elbows. They also repaired known damage as well as damage found during inspections. This included repair work on 16 air flow dividers and two throat sections which had been damaged enough to warrant repair. All repairs were completed within the outage window.


After initial coal feeder issues, the performance of the burners have been good. NOx levels have been able to be met without over-fire air with most coals to-date. Air adjustments to maintain burner and tip temperatures under alarm limits are continuing as different pulverizers are taken out of service.

Air flow dividers designated to replace. Additional ones may be added after injectors pulled. 8th Floor



















7th Floor
















6th Floor

















5th Floor

















West


Front wall looking North

East









































5th Floor















East


Rear Wall Looking South

West






West



Front wall looking North (Tips to have air sleeve moved back.) Tip to be replaced


East


East



Rear Wall Looking South (Tips to have air sleeve moved back) Tip to be replaced

West





Inner air sleeve settings ABT Burner
Inner air sleeve has 12 holes in the handle. With the bolt through the 12th hole (showing 11 holes) the sleeve is closed. With sleeve pushed in with the bolt in the 1st hole, opening 6 1/4 " opening. Below is a list with measured opening per bolt in each hole.

bolt in XX hole	opening "	_
12th	0	closed
11th	1/2	
10th	1 1/4	
9th	1 3/4	
8th	2 3/8	
7th	2 7/8	present '06 setting 7th in from handle, 7th from full open
6th	3 3/8	
5th	3 7/8	
4th	4 7/16	
3rd	5 1/16	
2nd	5 3/4	
1st	6 1/4	full open, all the way pushed in

opening			calc'd		
1st	6 1/8	full open	6 3/16		
2nd	5 1/2		5 10/16		
3rd	4 7/8		5 1/16		
4th	4 1/4		4 8/16		3rd to 7th hole with
5th	3 3/4		3 15/16	as left	new nozzles installed '08
6th	2 15/16		3 6/16		
7th	2 1/2		2 13/16	as found	setting after '06 outage
8th	2		2 4/16		
9th	1 11/16		1 11/16		
10th	1 1/16		1 2/16		setting '04 to '06
11th	11/16		9/16		
12th	0	closed	0		

- 1- save bolts and nuts on elbow and injector
- 2- pull all elbows and injectors
- 3- make sure proper orientation injector in proper spot CW vs CCW all burners are marked, also shown on work sheet
- 4- Air flow divider put bevel end furnace side and install with seam at 6 o'clock position (bottom) Worst 12 have been marked on drawing. Inspection will determine the next twelve to be repaired if needed.
- 5- Injectors will still be coming in after start of outage. Leave C row (6th level on back wall last) incase they do not arrive in time. Put new elbows only on new injector. Therefore do not remove old elbows and injectors from burner level until replaced by new parts. Worst case we will have to repair some old injectors and move to needed levels.

D1 and D3 have the reversed TC locations

	Present	1	New		to annual	and of one has	New	in conde	out-of-service
	elbow temp	intermediate	burner tip	pt to initiate	in-service	out-of-service	burner barrel	in-service	
B1	2sgate1536	2sgate1537	2sgate1536	2SGAES0006	800	1400	2sgate1537	650	1200
B2	2sgate1402	2sgate1403	2sgate1402		800	1400	2sgate1403	650	1200
B3	" "1538	" "1539	" "1538		800	1400	" "1539	650	1200
B4	" "1408	" "1410	" "1408		800	1400	" "1410	650	1200
B5	" "1540	" "1541	" "1540		800	1400	" "1541	650	1200
B6	" "1412	" "1414	" "1412		800	1400	" "1414	650	1200
F1	" "1416	" "1418	" "1416	2SGAES0010	800	1400	" "1418	650	1200
F2	" "1542	" "1543	" *1542		800	1400	" "1543	650	1200
F3	" "1420	" "1422	" "1420		800	1400	" "1422	650	1200
F4	" "1544	" "1545	" "1544		800	1400	" "1545	650	1200
F5	" "1428	" "1430	" "1428		800	1400	" "1430	650	1200
F6	" "1546	" "1547	" "1546		800	1400	" "1547	650	1200
A1	" "1548	" "1549	" "1548	2SGAES0005	800	1400	* "1549	650	1200
A2	" "1432	" "1434	" "1432		800	1400	" "1434	650	1200
A3	" "1550	" "1551	" "1550		800	1400	" "1551	650	1200
A4	" "1436	" "1438	" "1436		800	1400	" "1438	650	1200
A5	" "1552	" "1553	" "1552		800	1400	" "1553	650	1200
A6	" "1444	" "1446	" "1444		800	1400	" "1446	650	1200
E1	" "1448	" "1450	" "1448	2SGAES0009	800	1400	" "1450	650	1200
E2	" "1554	" "1555	" "1554		800	1400	" "1555	650	1200
E3	" "1456	" "1458	" "1456		800	1400	" "1458	650	1200
E4	" "1556	" "1557	" "1556		800	1400	" "1557	650	1200
E5	" "1460	" "1462	" "1460		800	1400	" "1462	650	1200
E6	" "1558	" "1559	" "1558		800	1400	" "1559	650	1200
G1	" "1479	" "1478	" "1479	2SGAES0011	800	1400	" *1478	650	1200
G2	" "1564	" "1565	" "1564	ZOUALOUOTT	800	1400	" "1565	650	1200
G3	" "1475	" "1474	" "1475		800	1400	" "1474	650	1200
G4	" "1562	" "1563	" "1562		800	1400	" "1563	650	1200
G5		" "1466	" "1467		800	1400	" "1466	650	1200
G6	" "1467 " "1560	" "1561	" "1560		800	1400	" "1561	650	1200
C1	1.14570	W W4 574	11 11 170	000450007	900	1400	" "1571	650	1200
C1	" "1570	" "1571	" "1570	2SGAES0007	800	1400	* *1494		1200
C2	" "1495	" "1494	" "1495		800	1400	" "1569	650	
C3	" "1568	" "1569	" "1568		800	1400		650	1200
C4	" "1487	" "1486	" "1487		800	1400	" "1486 " "1567	650	1200 1200
C5 C6	" "1566 " "1483	" "1567 " "1482	" "1566 " "1483		800 800	1400 1400	" "1482	650 650	1200
						1.100	B. 84.540	050	1000
H1	" "1511	" "1510	" "1511	2SGAES0012	800	1400	" "1510	650	1200
H2	" "1576	" "1577	" "1576		800	1400	" "1577	650	1200
H3	" "1507	" "1506	" "1507		800	1400	" "1506	650	1200
H4	" "1574	" "1575	" "1574		800	1400	" "1575	650	1200
H5	" "1499	" "1498	" "1499		800	1400	" "1498	650	1200
H6	" "1572	" "1573	" "1572		800	1400	" "1573	650	1200
D1	" "1582	" "1583	" "1582	2SGAES0008	800	1400	" "1583	650	1200
D2	" "1527	" "1526	" "1527		800	1400	" "1526	650	1200
D3	" "1580	" "1581	" "1580		800	1400	" "1581	650	1200
D4	" "1519	" "1518	" "1519		800	1400	" "1518	650	1200
D5	" "1578	" "1579	" "1578		800	1400	" "1579	650	1200
D6	" "1515	" "1514	" "1515		800	1400	" "1514	650	1200